

15.559 SE: 82 Appleton Street: Replace 9 windows (wood).
15.556 SE: 34 Braddock Park: Replace 5 windows (wood).
15.518 SE: 10 Cazenove Street: Replace 3 windows (wood).
15.513 SE: 476 Columbus Avenue: In-kind replacement of deteriorated wood fascia board and dentils at cornice; replace existing gutter with copper.
15.558 SE: 501 Columbus Avenue: Replace 4 windows (aluminum clad); replace deteriorated wood trim at windows.
15.496 SE: 505 Columbus Avenue: Replace 2 steps (both risers and treads) details to match existing; repair and repaint front entry stoop with HC-69.
15.553 SE: 35 Concord Square: Replace deteriorated concrete walkway to garden level under stoop entrance with stone (to match #37); repaint bottom step of front stoop with HC-69.
15.540 SE: 34 Dartmouth Street: Replace roof deck (**visibility must be reviewed by staff**).
15.551 SE: 23 Dwight Street: Replace 13 windows (wood).
15.541 SE: 484 Massachusetts Avenue: Repair stone curb and in-kind replacement of garden fence.
15.550 SE: 603 Massachusetts Avenue: Repoint masonry; repair brownstone elements including sills and lintels and repaint with HC-69; repair/repaint cornice and fascia; install copper gutters.
15.562 SE: Multiple Locations: Install bike racks at 20 locations.
15.547 SE: 1 Ringgold Street: Repoint masonry; repaint sills and lintels with HC-69.
15.548 SE: 308 Shawmut Avenue: Replace 11 windows (wood).
15.557 SE: 314 Shawmut Avenue: Replace 4 windows (wood).
15.561 SE: 515 Shawmut Avenue: Install mechanical vent at roof.
15.490 SE: 514-518 Tremont Street: Masonry repairs; re-install damaged stones.
15.545 SE: 597-599 Tremont Street: Repoint masonry; repaint wood window trim.
15.552 SE: 619 Tremont Street: Replace flat rubber roof and associated edge flashing at dormer.
15.519 SE: 789-793 Tremont Street: Replace flat rubber roof and associated edge flashing.
15.555 SE: 35 Union Park: Replace gutters; in-kind replacement of deteriorated wood at fascia; repair wood at cornice and repaint; repoint masonry; repair sills and lintels; repaint brownstone elements including sills, lintels, entry surround and front entry stoop with HC-69; repaint window trim (black).
15.566 SE: 39 Union Park: Install new mechanical equipment platform at roof; repair/repaint wood cornice; repair/repaint sills and lintels; restore detail at lintel; spot repointing/cleaning of masonry; repair front entry stoop; repair balustrades at front garden railing; install shutters (exempt); install new deck at rear (exempt).
15.560 SE: 16 Upton Street: Replace 10 windows (wood).
15.546 SE: 1666 Washington Street: Replace existing skylight.
15.565 SE: 1670 Washington Street: Repoint brownstone above 1st floor; remove paint at first floor and garden level and repaint; in-kind replacement of asphalt shingles at roof.
15.554 SE: 1747 Washington Street: Replace signage.

PROJECTED ADJOURNMENT: 6:30 P.M.

Date posted: October 24, 2014

Mayor, Inspectional Services Department, City Clerk, Boston Redevelopment Authority, Applicants, District City Councilors,
Neighborhood Services, Property Owners, Law Department, Abutters (from most recent tax list)
For additional information, please contact South End Landmark District Commission staff at 617-635-3850